



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil Gas and Mining

JOHN R. BAZA
Division Director

September 7, 2007

Mr. John Burggraf, Vice President – Excavation Division
Lakeview Rock Products, Inc.
900 North Redwood Road
North Salt Lake, Ut 84054

Subject: Request for Changes to the Notice of Intention and Immediate Actions, Lakeview Rock Products, Inc., Thomas Pit, M0110002, Davis County, Utah

Dear Mr. Burggraf:

Division personnel, Ms. Beth Ericksen and Mr. Dan Smith visited the Thomas Pit site on September 6, 2007, which has resulted in the following request for action items associated with the permit NOI and the implementation of additional requirements to ensure compliance is maintained and among other practices, specifically, that the subject property meets public safety and welfare practices.

The list below identifies the necessary action and whether this action is affiliated with the current plan that will require an amendment (A) or if the action required is a result of not following the plan (NOI) outline (I). As shown in the table, the required change is identified along with referencing the particular rule, picture number and deadline.

Action Description	A or I	Required Change	Rule	Picture reference	Deadline
Place warning signs where public access is readily available	I	Implement	R647-4-107.1		September 26, 2007
Gated entrance from frontage road	A	Gate(s) will be closed and locked when operations are closed.	R647-4-107.1	2007.09.06 10:08	September 26, 2007
Warning signs placed on access roads advising of blasting protocols	I	Implement	R647-4-107.1		September 26, 2007


Install public warning signs every 100 feet at the safety berms above the highwall(s)	I	Implement	R647-4-107.1		September 26, 2007
Fence the eastern property boundary with t-post and 4 foot wire fence topped with 2 strands barbed wire	I	Implement	R647-4-107.1		September 26, 2007
Gated entrance from developing neighborhood	A	Gate will be closed and locked at all times.	R647-4-107.1		September 26, 2007
Change company representative contact	A	From Russell Larsen to current contact	General Information (1.4)		September 26, 2007
Identify & describe a safe blasting plan	A	Call to discuss or arrange meeting with DOGM	R647-4-107.1		October 31, 2007
Erosion control (including access roads)	A	Call to discuss or arrange meeting with DOGM	R647-4-107.3	2007.09.06 09:18	October 31, 2007
Surface water control	A	Call to discuss or arrange meeting with DOGM	R647-4-107.3		October 31, 2007
Vehicle/equipment maintenance and storage of deleterious materials	A	Call to discuss or arrange meeting with DOGM	R647-4-107.1		October 31, 2007
South end highwall area, disturbed	A	Provide overview regarding the this area and how it is kept in an environmentally safe manner	R647-4-107.6	2007.09.06 09:01	October 31, 2007
Berms, topsoil	I	Implement/explain	R647-4-107.5	2007.09.06 09:02	October 31, 2007
Berm design	I	Trenches; (did not see trenching as described in plan)	R647-4-107.1		October 31, 2007
Map, figure 3A	A	Update; map does not reflect current conditions	R647-4-105		October 31, 2007

Page 3
Mr. John Burggraf
N0110002
September 7, 2007

The Division looks forward to working with you on the plan modifications as required by rule. This effort is geared toward fostering a culture of ensuring the welfare and safety of the public and instilling the importance that the mining industry is respected, valued and highly regarded as its role is critical toward the economic vitality and high quality of life the citizens of the state experience and deserve.

A copy of the inspection report is forthcoming under separate cover. If there are any questions regarding the content of this letter, please contact Ms. Beth Ericksen, 801-538-5318.


Sincerely,

for 
Susan M. White
Mining Program Coordinator
Minerals Regulatory Program



The wall is not being raised (looking south)





unworked face

pipeline
for dust
suppression

first bench,
upper level


looking south

2007-08-08

access road ve
neighborhood

looking east

this may be part of the 100 feet set back area



2007-09-06 10:00

From: Origin ID: NPHA (801)538-5304
Vickie Southwick
Division Oil Gas Mining
1594 West North Temple Suite 1210

Salt Lake City, UT 84114




CLS832987/2/1/23

SHIP TO: (801)292-7161 BILL SENDER

JOHN BURGGRAF
LAKEVIEW ROCK PRODUCTS INC
900 NORTH REDWOOD ROAD

NORTH SALT LAKE, UT 84054



Ship Date: 07SEP07
ActWgt: 1 LB
System#: 5414880/INET2600
Account#: S *****

Delivery Address Bar Code



Ref #
Invoice #
PO #
Dept #

TRK# 7997 1035 3978
0201

MON - 10SEP A1
STANDARD OVERNIGHT

WM-SLCA

SLC
UT-US
84054



Shipping Label: Your shipment is complete

1. Use the 'Print' feature from your browser to send this page to your laser or inkjet printer.
2. Fold the printed page along the horizontal line.
3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$500, e.g. jewelry, precious metals, negotiable instruments and other items listed in our Service Guide. Written claims must be filed within strict time limits, see current FedEx Service Guide.